

June 7, 2021

Mr. David J. Keating
Wetlands Enforcement Officer
Town of Beacon Falls
10 Maple Avenue
Beacon Falls, CT 06403-1198

Re: Chatfield Farms – Phase 4B, 4C and 5, June 7th, 2021 Sedimentation and Erosion Control Inspections

Dear Mr. Keating:

At the request of EG Homes, LLC we will be conducting Sedimentation & Erosion Control Inspections for the Phase 4B, 4C and 5 Construction areas. These sedimentation and Erosion control Inspections will be conducted monthly during the 1st week of the month, and after significant rainfall events.

During our June 7th inspections, we found the following:

- Phase 4B;
- Perimeter silt fences are all in place and in good condition. two short sections of silt fence behind units #29 & 30 have sediment build-up.
- All silt fabric in the catch basins is intact.
- The paved portion of the road has dirt tracked onto it from the un-paved Cul-De-Sac and from the Soil screening operation adjacent to the upper roadway.

Phase 4C;

- Perimeter silt fences are all in place and in good condition.
- The anti-tracking pad has had new stone added to it
- All silt fabric in the catch basins is intact.
- The pavement adjacent to the anti-tracking pad has sediment on the roadway.

• Phase 5;

- There is sediment build –up on the roadway adjacent to the three existing catch basins with filter fabric.

Attached are photographs taken today during the Inspection, separated and labeled by phase.


Regarding the inspection we make the following recommendations:

- Phase 4B: The sediment build-up along the silt fence should be removed, and the roadways should be swept.

June 7, 2021
Mr. David J. Keating
2 / 2

- Phase 4C: The roadway adjacent to the Construction Entrance should be swept.
- Phase 5: The sediments in the road at the three catch basins should be swept up.

Sincerely,
DeCARLO & DOLL, INC.



Ronald J. Nault, P.E.
President – Project Manager



PHASE 4B - SILT @ SILT FENCE



PHASE 4B - DIRT ON PAVED ROADWAY



PHASE 4 C - DIRT ON ROADWAY @ CONSTRUCTION ENTRANCE



PHASE 5 - SEDIMENTATION BUILD UP @ CATCH BASIN (TYP. OF 3)